

Gleason Energy Saver Package

**to save energy
while machine is waiting for blanks.**

A machine, waiting for blanks, should not be aloud consuming energy for nothing. To avoid consuming energy for nothing, the Gleason Energy Saver Package shuts down the machine in five steps.

If blanks available the machine starts partial up automatically and goes back into production.

	Basic package	see pricelist below	Options	price on request
Step 1	Machine light off manual over switch		Machine light off over timer. Customer defines on/off timer Upgrade to LED lamp in working area	
Step 2	Chip conveyor and vacuum cleaner off if machine on hold. Restart automatically (shut down over timer)		Stop working Spindle and axis-drive cooling unit. Restart with confirmation.	
Step 3	Automation/conveyor off, if no parts available. Restart with confirmation.		Restart automatically, but only with Pokajoke (blank checking)	
Step 4	Drives and hydraulic off after XX minutes. Restart by operator		Unload machine, with Pokajoke (blank checking)	
Step 5	Air barrier off after XX minutes and step 4. Restart with confirmation		Restart machine with warm-up program at defined time to bring the machine back to working temperature for next shift.	

The upgrade of the basic package can be done within one day.
The duration of installing options is related to machine configuration.

**Depending on machine type,
operating scheme and amount of
shifts, financial savings per year can
be € 2.000.-**

	Price for basic package in Euro
P 60	3,000.-
P 90	3,000.-
P 210 L	4,500.-
AGILUS	4,500.-



GEARING UP FOR 'GREEN'

Get Started Today!

Scan and email us:

service@gleason-pfauter.ch or Fax: +41-32-365 3003

Contact me about:

Basic steps 1 to 5

☐ Gleason Energy Saver Basic
step 1 to 5

Options for steps 1 to 5

- ☐ Step 1 Automatic machine light on/off
- ☐ Step 1 Upgrade to LED lamp
- ☐ Step 2 Stop working spindle and
axis-drive cooling unit
- ☐ Step 3 Automatic restart
- ☐ Step 4 Unload machine
- ☐ Step 5 Automatic restart in warm-up program

Name _____

Titel _____

Company _____

Address _____

Zip code _____ City _____

Country _____

Telefon _____ Telefax _____

e-mail _____

Machine model _____ Serial No. _____

Gleason Field Service Offices

Argentina

Buenos Aires
Tel. +54 11 4521 2001

Australia

Parramatta
Tel. +61 2 963 347 99

Brazil

Sao Paulo (SP)
Tel. +55 11 3673 3844

China

Beijing
Tel. +86 10 5979 9907
Jiangsu (Suzhou)
Tel. +86 512 6271 8767

Czech & Slovak Republic

Brno
Tel. +420 5 111 204 90

Finland

Vantaa
Tel. +358 989 551

France

Roissy CDG Cedex (Paris)
Tel. +33 (0)1 493 890 00

Germany

Kassel
Tel. +49 (0)561 31 09 96 0
Ludwigsburg
Tel. +49 (0)7141 404 0
Munich
Tel. +49 (0)89 35401 0

India

Bangalore
Tel. +91 802 852 4376
Mumbai
Tel. +91 222 836 2354
New Delhi
Tel. +91 115 544 1803

Italy

Bologna
Tel. +39 05 135 196 11

Japan

Tokyo
Tel. +81 (0)3 5560 2801
Nagoya
Tel. +81 (0)6 2804 7211
Osaka
Tel. +81 (0)6 6202 4111

Mexico

Mexico, D.F.
Tel. +52 5277 5545
Queretaro, Qro
Tel. +52 442 2189 340

South Korea

Seoul
Tel. +82 2 210 405 00
Kyunggi
Tel. +82 31 387 2961

Spain

Barcelona
Tel. +34 93 24 564 07

Switzerland

Studen
Tel. +41 (0)32 3 66 61 71

Sweden

Västerås
Tel. +46 21 12 94 10

Taiwan

Taipei
Tel. +886 2 277 231 35

United Kingdom

Plymouth, England
Tel. +44 (0)1752 724 424

United States

Rochester, NY
Tel. 800 765 6525
Dayton, OH
Tel. 800 765 6525
Farmington Hills, MI
Tel. 800 765 6525

www.gleason.com • service@gleason.com

Visit www.gleason.com for Worldwide Sales Locations and Additional Information.